

**Subject:** CORRECTION: Photo Release: Salvage Operations Continue on Barge DM 932  
**From:** jaclyn.a.young@uscg.mil  
**Date:** Thu, 31 Jul 2008 14:05:52 -0700 (PDT)  
**To:** Nickie <Nickie.Scillo@noaa.gov>

**DATE:** July 31, 2008 16:05:02 CST

**CORRECTION: Photo Release: Salvage Operations Continue on Barge DM 932**



## Photo Release

Date: July 31, 2008  
Contact: Joint Information Center  
(504) 393-0372



In this photo released by the U.S. Coast Guard, workers weld padeyes on to the damaged barge DM 932 that rests against the Crescent City Connection Bridge in the Mississippi River near downtown New Orleans July 31, 2008.

The padeyes are being put into place to facilitate the lift of the barge out of the water during salvage operations.

*(U.S. Coast Guard photo/Petty Officer 3rd Class Jaclyn Young)*



In this photo released by the U.S. Coast Guard, a padeye that will be used to assist in lifting the damaged barge DM 932 out of the Mississippi River during salvage operations.

The padeyes are being welded onto the barge.

*(U.S. Coast Guard photo)*

***The following photography hand-out is provided free of charge to duplicate and distribute as desired.***

###

CORRECTION: Photo Release: Salvage Operations Continue on Ba...

Visit this link to unsubscribe:

<http://www.piersystem.com/go/unsubscribe/1794/>